


Isolation procedure working on or near low voltage electrical systems & equipment



Re-energising process

1. Inspect & test (BS7671 dead tests)
2. Cancel permits (if any) remove lock off devices & labels then restore supply
3. Complete live tests and commission equipment
4. Complete & issue appropriate certificates/reports.